

FIG.1

DEFINITION	
APPOINTMENT 19	bw_remaining 13
INITIAL VALUE	
0	4915
READ-IN VALUE	
0	DIRECTLY PREVIOUS SUCCESSFUL LOCK
EFFECT OF LOCK	
DISREGARDED	CONDITIONAL WRITING

FIG.2




FIG.3

FIG.4A





FIG.4B



	n	pa	pb	pc	pd	pe	pf	pg	ph
PACKET #1	0	p3	p4	p5	p6	p7	p8	p9	p10
PACKET #2	1	p11	p12	p13	p14	p15	p16	p17	p18
PACKET #3	2	p19	p20	p21	p22	p23	p24	p25	p26





FIG.5


FIG. 6

900h	Output Master Plug Register
904h	Output Plug Control Register #0
908h	Output Plug Control Register #1
⋮	⋮
97Ch	Output Plug Control Register #30
980h	Input Master Plug Register
984h	Input Plug Control Register #0
988h	Input Plug Control Register #1
⋮	⋮
9FCh	Input Plug Control Register #30


FIG. 7A



oPCR[n]



iMPR



iPCR[n]




FIG. 7D

FIG. 8




FIG. 9




FIG. 10





FIG. 11






FIG. 13




FIG.14




FIG. 15




FIG. 16




FIG.17




FIG.18



FIG. 19